


MONUMENT ACCESSORIES

Other survey grade monuments that were located in the vicinity and their relation to the monument.
Geodetic coordinates in this table are provided in the format Easting, Northing.

(#10096)	S 0d37'25" E	39.61' (m) 39.6' (original falling)	3097237.95, 1432109.29 1" iron pin found flush in concrete on the south side of Vernal Pike at the section corner common to Sections 25 & 36 -T09N-R02W (Rich_Y21)
(#10117)	S 67d1'32" W	70.96'	3097172.19, 1432121.20 Cut X in the southwest back of curb inlet
(#10120)	N 76d56'45" W	68.07'	3097171.21, 1432164.27 Cut X in the northwest back of curb inlet
(#10123)	N 78d19'20" E	90.61'	3097326.26, 1432167.24 Cut X in the northwest back of curb inlet
(#10126)	S 74d24'31" E	91.98'	3097326.12, 1432124.18 Cut X in southwest back of curb inlet

N



OTHER ACCESSORIES:

Work done to preserve existing monument. A 5' steel t-post was set 0.5' north of the north face of a 5.6' tall limestone post on the south side of Vernal Pike. A Monroe County "PROTECT NEARBY SURVEY SIGN" was attached facing north 2.6' above grade.

NOTES:

- Field work was performed on 02/26/2019.
- Monroe County Surveyor's Field Book 53, page 35.
- Project Name: 2019-003_2019_INDOT_Network, Field work by: RSO & TER, Drawn by: RSO, Reviewed by: RSO, TER & SRB.
- The basis of bearings is Grid North NAD83(2011), Indiana West Zone, Epoch 2010.0000, Geoid Model G2012BU7, Datum NAD83_NO_TRANS, US Survey Feet, derived from GPS observations utilizing the Indiana Real-Time Network (INCORS). Distances obtained with GPS have not been adjusted to ground. Coordinate data was collected with a Javad Triumph LS Network Rover.
- Vicinity sketch was compiled per 2017 aerial photography.
- This monument was set during Vernal Pike road improvements performed by the Monroe County Highway Department and INDOT. The monument was set at the record falling north of the found monument at the Southeast corner of Section 30-T9N-R2W (Rich_Y21), on line with the monument found at the Northeast corner of the Southeast Quarter of Section 30-T9N-R2W (Rich_Y19). For monument origin see Vernal Pike Route Survey recorded as Instrument Number 2008006523 and Vernal Pike Plan and Profile on file in the Monroe County Surveyor's Office as RSID002741. We collected coordinates on the new monument to perpetuate its location. Historic research has not yet been performed to prove the validity of this monument.

▲ **Monument Description:** 1" iron pin found flush in concrete in the north yellow line of the turn lane of Vernal Pike and in line with fence remains to the south and a tree line to the north

State Plane Grid Coordinates: Point No.: 10107 Northing: 1432148.90', Easting: 3097237.52'

SHEET
1
OF
2

MONUMENT RECORD
CORNER ID:
Blm_A21

Section Corner
Section 30 & 31- T09N-R01W
Bloomington Township
Monroe County, Indiana



OFFICE OF THE MONROE COUNTY SURVEYOR
Trohn Enright-Randolph Monroe County Surveyor
Rachel Savich Oser Professional Surveyor
119 West 7th Street, Bloomington, IN 47404 (812) 349-2570

Photos were taken on 02/26/2019 with an iPhone 6s



Trohn Enright-Randolph
Trohn Enright-Randolph
Monroe County Surveyor



Accepted by the Monroe
County Surveyor Review Board
on 07/02/2019



Rachel Oser
Rachel Savich Oser, State of Indiana
Professional Surveyor No. 21100022

SHEET
2
OF
2

MONUMENT RECORD
CORNER ID:
Blm_A21

Section Corner
Section 30 & 31- T09N-R01W
Bloomington Township
Monroe County, Indiana



OFFICE OF THE MONROE COUNTY SURVEYOR
Trohn Enright-Randolph *Monroe County Surveyor*
Rachel Savich Oser *Professional Surveyor*
119 West 7th Street, Bloomington, IN 47404 (812) 349-2570